

14 MAY 1930

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc.Sr. "GLANBRYDAN" Rpt. Nwc. No. 85607**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

It is submitted before this case receives the consideration of the Committee the Surveyors should be requested to state whether they are correct in reporting the vessel to have 210 fathoms of chain cable on board in view of the fact that she was originally supplied with and still requires 240 fathoms.

Classing dr 9/5/30

© 2020
9.5.30.Lloyd's Register
Foundation

W280-0031