

For the information of Surveyors and the Committee only.

Received at

Office,

19

Lloyd's Register of Shipping.

(Report on Machinery, No. Port

No. ¹⁰⁵ ~~F-143~~ ENGINE FORGINGS OR CASTINGS.

I have to report that the ~~Iron or~~ Steel Forgings ~~or Castings~~, as herein described, manufactured by Canada Forge Company, Welland, Ont Supply
for the ~~Engines~~ ^{Order} No. 5961 being constructed by International Machine & Co. Ltd
of Montreal, Can. for the Ship No. ✓, being built by
Tidewater S.B. Company. of Three Rivers, Que.
have been inspected by me as set forth below, and found to be, so far as can be
seen sound 6 Line Shafts

14-4-21

LLOYDS	LLOYDS	LLOYDS	LLOYDS	LLOYDS
No. 2294	No. 2298	No. 3021	No. 3042	No. 3043
30-3-21	2-4-21	6-4-21	13-4-21	13-4-21
J.W.J.	J.W.J.	J.W.J.	J.W.J.	J.W.J.

W. Widdell
Buffalo N.Y.

GRANK SHAFT. 2293	STRAIGHT SHAFTING.		
	2294 THRUST SHAFT.	2298 INTERMEDIATE SHAFTS.	3021 PROPELLER SHAFT.
	O.H. Steel		
	Forged and machined		
	15" dia. 19-10 1/2" long.		
	Rough Machined		
Standard Pieces.			
Test --			
per square inch.	69440	70880	70000
on per cent	29.65	29.65	29.65
ling Test --			
fore fracture.	180	180	180
on Inspected	30-3-21	30-3-21	2-4-21

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS.


No. 3042	No. 3043
69200	71320
32.8	28.1
180	180
13-4-21.	13-4-21

charged

(if any ~~chargeable~~) £
To be paid at

of iron, state whether scrap or puddled iron. If of steel, state whether made on the Open Hearth process.

R. & C. Co.



© 2020

Lloyd's Register
Foundation

W280-0094