



# Lloyd's Register of Shipping,

342, Argyle Street, Glasgow.

LLOYD'S REGISTER

Recd. 25 APR 1924

ATAA

LONDON

24th April, 1924.

Reference

Sir,

*61924*

I beg to acquaint you that the Owners of the steamer "GRETASTON" state that this vessel has developed a buckling in the bridge deck plating. The vessel is now at Hull and it was suggested to the Owners that Mr. Gibbs, the Society's Principal Surveyor at Hull, should examine her. In view of the fact, however, that a sister vessel is at present being constructed by Messrs. Lithgows, Ltd., the Owners wished that a surveyor from this office should attend and inspect the damage, and they stated that they had communicated with you and had been informed that there would be no objection to this course being followed provided the Chairman of the Glasgow Committee agreed. In these circumstances, Mr. R. D. Cairns was instructed to proceed to Hull and he has left for that Port this morning.

I am, Sir,

Your obedient Servant,

© 2020

Lloyd's Register  
*L. H. Warlow*  
 Foundation  
 Secretary to the  
 Glasgow Committee.

The Secretary,  
 LONDON.

W282-0184

Referred to Chief Ship Surveyor.

af  
25 APR 1924

Also for Mr. S. A. Hill to note.  
Also for Mr. Maxine to note.

F. E. McAuley

The owners telephoned to me &  
I informed them that the  
matter would should be  
referred to the Chairman  
of the Glasgow Com.  
W.A.

Spl.  
—



© 2020

Lloyd's Register  
Foundation