

Plus with rubber Surveys etc

Lloyd's Register of Shipping,

342, Argyle Street, Glasgow.

1st October, 1921.

Dear Sir,

With reference to the London letter of the 29th September regarding the report No. 41350 on the Steamer "MATAKANA", I have to state that reversed angles are fitted to the ^{chamfer} stiffeners of bulkheads 27,46; 128 and 155, a semi-box beam is fitted to the collision bulkhead at the level of the lower stringer, the butts of the bottom shell plating are quadruple riveted to the collision bulkhead, two web frames each side are fitted in No. 6 hold, and the tank top plating is increased under the hatchways where the tank top is not insulated, all as approved.

I am, Dear Sir,

Yours faithfully,

Geo. Webster

The Secretary,
GLASGOW.



© 2019

Lloyd's Register
Foundation

W284-0049