

1509, 10, 17.

1

Sent to Chief Surveyors 18.4.18

Received from Chief Surveyors

VESSEL'S NAME

Shells Polycarp

Report

66

No.

37679**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

1st Enlg -

When due

It should be noted in the Special reasons list that a special examination is to be made of the double bottom in Engine & Boiler space when the ss. hot is held

19.4

* 100A-1 (Steel)

200 (Steel)

Cell D.B. 288, 4200 F.P.T. 600 A.P.T. 750

F.K. 6 B.H. pl asp pt-cm Llyds arep.

P42.. B88 F 41

M
18.4.18

© 2019

Lloyd's Register
Foundation

W284-0126