

Floyd's Register of Shipping
S.S. "POLYCARP".- Messrs. Barclay Curle & Co's No. 540.

It is submitted the Glasgow Surveyors be requested to state why the instructions as to the use of Portland cement on the bottom in way of engine and boiler space, contained in the Secretary's letter of 3rd December last, have not been carried out without their drawing the attention of the Committee to the fact that such was not being done.

Lv. - 8.1.18.
Ansd. 10.

Ct.

9.1.18.

To 10/1/18



© 2019

Lloyd's Register
Foundation

W284-0133
W290