

to Chief Surveyors _____

Received from Chief Surveyors _____

SEL'S NAME Stl. S.C. m/v British Diplomat Report Gls No. 45790

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/02.)

Time of Survey 1st Entry When due _____

* 100 A.1 (Stl) Carrying petroleum in bulk
2 dks (stl) Web frames & Longitudinal framing
Cell 210 & E 58' 2326. DTf 34' 3885. FPT 195 APT 1775
FK. 18 BH. (12 to upper deck) fit. Conn. Slays A & CP
P 95' B 35' F 47' Weby aft

© 2020

Jan 4/7/22

It is concluded the ^{letter} ~~reporting~~ ^{approval} of the
hulls of the steel plating is approved and
the Surveyors should be requested to state whether
this is so.

Lloyd's Register
Foundation
8.7.15

W289-0056