

COPY. *For Reference*

D1788.

Lloyd's Register of Shipping.



Port LONDON,

24th May, 1939.

This is to Certify that

T. D. SCOTT,

the undersigned Surveyor to this Society did at the request of Messrs. Ronald Trist & Co., Ltd., Buxton, attend at their Works on the 17th May, 1939, for the purpose of examining and testing one Type "A" Thermofeed feed water regulator, made to the order of Messrs. The Clarkson Thimble Tube Boiler Co., Ltd., (order No. 2674/19/59) and intended for Messrs. Harland & Wolff, Ltd., of Belfast, order No. EW/15189 (Blue Star Liner).

The feed water regulator was examined, the float chamber and piping tested hydraulically to 425 lb. per square inch, the control valve to 200 lb. per square inch and all found sound and tight at the respective pressures.

For purposes of identification the float chamber was stamped thus:- LLOYD'S TEST 425 lb./sq." 17.5.39 *J.L.F.*
and the control valve thus:- LLOYD'S TEST 200 lb./sq." 17.5.39 *J.L.F.*

MAY 27 1939

T.D. Scott

Surveyor to Lloyd's Register of Shipping.

See:- 31.1.0

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."