

Kellesund

Bl 4937

Submitted that before this
case receives consideration the
surveyors be asked to state whether
the steam pipes were examined &
tested & if so whether the electric
light installation, if any, was
examined & tested.

Classified
to all



© 2019

1916/17
Lloyd's Register
Foundation

W295-0186