

S.S. "EIKUNDASUND", No. 14681 in R.B., built in 1916 by
Johs.Berg of Delf, and never classed with this Society.


A letter has now been received from the Owners in
which they state that the vessel is drydocking at Wivenhoe,
and they request the necessary survey may be held with a
view to obtaining this Society's class, and also to have a
freeboard assigned.

They state that the machinery and the tank are now
opened up and ready for survey, and the Surveyor is requested
to attend on the 1st September in order to survey the propeller
shaft.

It is submitted the Ipswich Surveyors should be
given the necessary instructions, and informed that there are
no plans in this Office nor any information other than that
recorded in the Register Book.

In the circumstances they should ascertain from the
Owners' representative whether it is possible to obtain plans
and forward them to this Office for examination with a view
to ascertaining for what class the ship is eligible.

In the meantime in view of the vessel being opened
up and in dry dock, they should proceed with the requirements
of Section 48 of the Rules relating to ships not built under
survey, and if it is not possible to obtain plans from any
source it will be necessary for scantlings of the vessel to be
taken by actual measurement at the ship and particulars of the



W295-0247 (1/2)

same forwarded to this Office on First Entry report forms for the consideration of the Committee, with as little delay as possible.

it is submitted
A copy of the letter sent the Ipswich Surveyors should be forwarded to the Owners for their information.

Full particulars on Form 11b should be forwarded to this office for freeboard assessment.

JM

31.8.21

JM

J.W.B.
8-9-21

Lr. Ipswich 1/9/21
Lr. Owners 1/9



© 2019

Lloyd's Register
Foundation

W295-0247 (2/2)