

M. S. "Badger State"

Report 3884 No.

OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in of an inch.

AMIDSHIP.					FORWARD.					AFT.					REMARKS.
Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
	Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
New	.62	.62	New	New	New	.62	.62	New	New	New	.62	.62	New	New	
	.44	.44	None			.34	.34	None			.34	.34	None		
	.44	.44	None			.34	.34	None			.34	.34	None		
	.44	.44	None			.34	.34	None			.34	.34	None		
	.44	.44	None			.40	.40	None			.40	.40	None		
	.44	.44	None			.40	.40	None			.40	.40	None		
	.44	.44	None			.40	.40	None			.40	.40	None		
	.44	.44	None			.40	.40	None			.40	.40	None		
	.70	.70	None			.54	.54	None			.54	.54	None		

Drillings at ends to be made in the vicinity of the peak bulkheads.

W297-0255

© 2019

Lloyd's Register Foundation