

9 - AUG 1934

"BADGER STATE"

Mtl 3884

This vessel was constructed in accordance with the
n 1912 and the class was subsequently withdrawn at the Owners'

New engines built under Special Survey in 1928-4 were
ed in the vessel in that year.

A report has now been received from the Montreal
r stating that the machinery has been examined with a view to
ification with this Society.

The machinery and electrical equipment have been
d throughout and placed in good condition, afterwards tested and
atisfactory.

The Philadelphia Surveyors report on account of
er striking an obstruction, the propeller shaft was examined and
er, found damaged, has been renewed.


It is submitted that this vessel is eligible for
ords †LMC 5,34 S.5,34 CL.
†NE 4,28

In Register Book, Col 13.

Oil Engines - 4 S.C.S.A. 6 cy. 18" - 22" N.H.P. 190.
Makers Bessemer Gas Engine Coy., Grove City, U.S.A.

Submitted the Montreal Surveyor be requested to obtain
Makers a sketch shewing the particulars of the riveting,
s and tenacity of material of the air receivers forwarding same
Office and he should be reminded that in all future similar cases
P.T.O.

W297-0259



ld be taken that all the particulars as requested in the
o the Committee ~~be~~ given. The Surveyor should also
hat the pumping arrangements are in accordance with the

Yes
See letter 25/8/24

Yours
P. P. 34

W297-0259



© 2019

Lloyd's Register
Foundation