



Lloyd's Register of Shipping.

Royal Bank Buildings,
28, Constitution Street,

LLOYD'S REGISTER,
LONDON.

Leith, 20th January, 1923.

REC'D 22 JAN 1923

Dear Sir, ANSO

S.S. "CORONDA" Leith Report No. 16,240.

In reply to your classing letter of the 19th instant, I beg to state that the butts of the shell plating at the turn of the bilge are in my opinion efficient until the next Special Survey, providing no further chafing takes place.

With reference to the close ceiling, the whole of this was removed from the tank tops and at the bilges, with the exception of the cross bunker space and lower side bunkers which still require to be examined as part of the work to complete the Special Survey as stated in the report. No. 3 Double Bottom tank requires to be examined internally in its entirety.

I am, Dear Sir,

Yours faithfully,

Robt. Cheetham.

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

W300-0143

Tam,

22 JAN 1923

24-1-23

1977-1978

1907

• 1957 12 18 1957 12 18

- 1940-1941
- 1941-1942

[illegible]

773

© 2020

Lloyd's Register
Foundation