

~~WRECK SECTION No. 13077~~
REPORT OF TOTAL LOSS, CASUALTY, &c.

No. 78954 in R.B. Wreck Book, p. 42/46 Date of writing this report Bot 30/10 31st October, 1946

Vessel's Name S.S. "Monte Isabela" of Bilbao Tons (Gross 3673 Net 2096)

Built at Stockton When 1921 3 Casualty notice sent to Owner 11.10.46 Owner's reply x

Owner's Name Naviera Aznar Sociedad Anonima
Address Apartado 13, Bilbao, Spain

| Case previously before Classing Committee. | Date | Particulars of Classification. | |
|---|------|--------------------------------|--|
| | | Last Minute | <u>+100A1</u> <u>Shelter dk</u> <u>with fbd</u> <u>3.46</u> <u>SS2nd No3-346</u> |

Casualty 20th September, 1946

particulars of Casualty

Struck Gando Rock, near Las Palmas, and
sank on the 20th September, 1946.

No reply has been received to the casualty
notice addressed to the Owners on the 11th ultimo.

SOURCE OF INFORMATION.

MONTE ISABELA.—Las Palmas, Sept. 21.—Spanish steamer Monte Isabela, Las Palmas for Cuba, in ballast, sailed at 6 p.m. on Sept. 20 and is reported to have struck Gando Rock at about 8 p.m. Vessel sank, two of crew missing. Madrid, Sept. 21.—
Two of the crew are missing after the Spanish steamer Monte Isabela sank off Gando, near Las Palmas, Grand Canary, after striking a reef, reports reaching Madrid said to-day. Thirty-two of the crew were picked up. The Monte Isabela is considered to be a total loss, according to these reports.—Reuter.

LL 23/9

MONTE ISABELA.—Bilbao, Sept. 23.—Spanish steamer Monte Isabela, sunk on Sept. 20 near Canary Islands when proceeding in ballast to Cuba, is a total loss; one member of crew lost. (See issue of Sept. 23.)

" 24/9

MONTE ISABELA.—Las Palmas, Sept. 25.—According to the local Press, it is believed that the Spanish steamer Monte Isabela sank owing to an explosion, as survivors state that the funnel blew up a quarter of an hour before the vessel sank. (See issues of Sept. 23 and 24.)

" 5/10

No 25 please

Suggested Record
Date of Committee
Committee's Minute

Wrecked 9.46
FRI. 1 NOV 1946

wrecked 9.46



© 2020
Lloyd's Register
Foundation

W304-0157

as Mps 7.11.46

Unit 860 S. 3.46