

30 SEP 1931

ed by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SEL'S NAME Steel Sc. "ALABAMA" Rpt. Gen. No. 12111

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

re of Survey _____

The class is subject to some rivets in the cargo tanks being renewed and cargo tanks retested before the vessel is again placed in commission and the repaired steering chains tested.

The Genoa Surveyors now report the vessel examined afloat, the necessary repairs effected and all cargo tanks tested and found tight and the repaired steering chains tested and found in order.

It is submitted the vessel appears worthy to remain as classed without record of survey and without special condition.

as now, without etc



© 2020

Lloyd's Register
Foundation

29.9.31

W305-0215