


IT IS SUBMITTED the Southampton Surveyors be
requested to state:-

- (1) whether the joints in the cables described
in their letter were made at the instigation
of the Owners' Engineer.
- (2) the number and designation of the cables so
jointed.
- (3) the number of joints in each cable.
- (4) whether the joints are in a dry position and at
all times accessible.



27.2.29.



© 2020

Lloyd's Register
Foundation

W306-0022