

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

21st December, 1937.

Dear Sirs,

M.

I am in receipt of your letter of the 20th instant in regard to the fees chargeable in connexion with the testing of the rudder stock and tiller arms for your Yard No. 847, and your remarks have been noted.

In reply I beg to inform you that the Society's fee for the special superintendence of the vessel during construction does not include the fees for testing steel plates, forgings, chain cable, etc. These fees are charged by the Society direct to the Manufacturers and are paid by the latter unless some special arrangement has been agreed upon between the Shipbuilders and the Manufacturers when the contract for the vessel was placed.

I am, Dear Sirs,

Yours faithfully,

Secretary.

Messrs. Philip & Son, Ltd.,
Sandquay & Noss Engineering Works,
DARTMOUTH.



© 2019

Lloyd's Register
Foundation

W307-0103