

Lloyd's Register of Shipping,

Botanicuslaan No. 23,

Haren-Groningen, the 3rd. of March, 1938



SURVEYOR:
L. H. WEHRMEYER.

E.

Gebr. Niestern's Yard No. 217
Motor yacht for Mr. Peter Crerar.



Dear Sir,

As desired by your letter of the 28th. of February, 1938, I discussed the matter of classification of the two Humboldt Deutz Engines intended for the above yacht with Mr. Niestern.

It appears from the information of the Humboldt Deutz representative at Rotterdam that Mr. Peter Crerar recently was in communication with the Engine-makers at Cologne regarding the above case, and he got apparently the answer that delay of delivery of the engines is depending on the fact that at present there is no crankshaft available on which the tests required by the Rules can be taken.

No further steps, regarding this matter have been taken now by the shipbuilders.

I am, Dear Sir,

Yours faithfully,

The Secretary,
LONDON.



L. H. Wehrmeyer

Lloyd's Register
Foundation

W307-0296

Lloyd's Register of Shipping

Referred to the Chief Engineer Bureau

[Handwritten signature]

RECEIVED
17th Dec 1938

TO THE CHIEF ENGINEER BUREAU

FROM THE CHIEF ENGINEER BUREAU

RECEIVED BY THE CHIEF ENGINEER BUREAU

RECEIVED
17th Dec 1938

RECEIVED BY THE CHIEF ENGINEER BUREAU



© 2019 Lloyd's Register Foundation