

Inspected by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

GIRARD

Rpt.

Hul

No. 50241

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/92.)

Date of Survey

2nd S.S. No. 2

due 6.39

The 2nd S.S. No. 2 has now been held, and the following repairs or renewals done:— To shell plating, framing, bulkheads, tunnel, deck plating and sheathing, casings, bulwarks, mizzen mast, rigging and minor repairs effected.

It is submitted the vessel is worthy to remain as classed, with record Survey 9.39 and notation of S.S. No. 2-39

100A1


Stm Trawler

9.39 Hul

ss Hul No. 2-39

f.e.d.

28.9.39



© 2021

Lloyd's Register
Foundation
W309-0118