

10.4.34.

5 E

12 NOV 1940

inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "ZEPHYROS"

Rpt.

Hav. No. 8477

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Record of Survey


DAMAGE-& WEAR AND TEAR.

The class is subject to the stern bush being examined before the end of 7.47; to the donkey boiler not being used; to the furnaces of the port boiler being examined and repaired by 11.46 and to stoppered tubes in the port and starboard boilers being renewed at the first opportunity.

All plain tubes in the port boiler now renewed.

It is submitted the vessel is eligible to remain as classed with

~~Record of Survey as recommended.~~ Subject as above with the exception of the renewal of stoppered tubes in the port boiler.



© 2019

Lloyd's Register
Foundation

12. 11. 46.

W311-0038

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances