

"SECURITY".

London	113172	Oct.1945	Boiler Survey	Nicholas & Sellex.
London	112311	Nov.1944	Annual Load Line Survey, Docking and Collision damage. Bottom examined, steering gear dismantled and examined. Wood belting renewed.	Jenkins.
			Also machinery report. B.S.	Chambers & Bedford.
London	112113	Sep.1944	Survey for condition on return to Owners. Tug placed on "hard" found deckhouse top leaking and belting damaged. Also machinery and boiler examined.	Widgery.
Sunderland	33926	Apr.1944	Docking and condition. Doublings fitted to garboard strake in way of boiler space. Also machinery.	Croudace. Home.
Newcastle	102013	Apr.1944	Leakage through bottom shell in boiler space. Temporary repair. Int. certificate.	Young.
Grimsby	21618	Oct.1943	Docking and minor repairs. Also B.S.	Smellie.
London	110794	Dec.1942	Docking, 3rd S.S. No.3 and repairs. Extensive repairs. Also L.M.C. and tailshaft.	Nicholas.
Greenock	21918	Jul.1942	Boiler repairs.	Trechmann.
Lon.	Fbd.1993	Mar.1946	Annual Load Line Survey.	Sellex.
Lon.	Fbd.1582	Nov.1944	Annual Load Line Survey.	Jenkins.
Gms.	Fbd.21666	Mar.1944	Annual Load Line Survey.	Smellie.
Lond.		Dec.1942	Load Line Renewal Survey.	Nicholas.



© 2019

Lloyd's Register
Foundation