

should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars

Large letters

GRAMS : REGISTER, CARDIFF.

TELEPHONE : 7553 & 7554 CARDIFF.



Lloyd's Register of Shipping,

Empire House, Mount Stuart Square,

Cardiff, 10th. June, 1938.

LLOYD'S REGISTER
Received
11 JUN 38
And.
LONDON

Dear Sir,

The steamer "NORTHGATE" is about to come under survey at this Port for alterations to the positions of the bulkheads forming the sand compartment, and if any approved plans for the work recently carried out at Blyth are available we shall be glad if these may be forwarded to us for our information and guidance.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

per:-

E. Brimblecombe.

The Secretary,
LONDON.



© 2019

Lloyd's Register
Foundation

W312-0127

W512-0128

sign
to v
in
su
7
lic
bu
mg
st
T.M.
if on
at on
ds, &
ow as
f rec
letter
o. of
er
ite if
h
n doc
length
Warp
id Bu
egiste
lassed
m

