

11/6/38.

d under steam?

5E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Northgate

Rpt.

Nov.

No.

96336.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

of Survey

~~DAMAGE & WEAR AND TEAR.~~

Alterations

This vessel has been converted for carrying & pumping sand in bulk.

A steam driven sand pump, fitted and steam pipe arrangement, also pumping arrangements modified to suit.
A new top manhole door fitted to the boiler.

It is submitted the vessel is eligible to remain as classed with

Board of Survey

as recommended.



© 2019

Lloyd's Register
Foundation

W312-0133