

YACHT

27 APR 1939

Received from Chief Surveyors

Chief Surveyors

NAME Ltd. Sc. Sch. Yacht "Marion" Report ✓ No. ✓

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

of Survey 4th S.S. No. 1 When due 7.36
TS due 7.34 + late 7.32

? General Examination.

UNDERTAKING CASE.

In September, 1933 the Owners wrote the yacht had not been commissioned during that year and was merely laid up for sale. She has been laid up ^{since} and action has been deferred accordingly from time to time pending recommission.

The 4th Special Survey No.1 became due 7,36.

The case received further consideration in July, 1937, the yacht was still laid up and an undertaking was asked for and furnished.

In reply to enquiry the Southampton Surveyors state that the vessel is still laid up.

The yacht does not appear to have been examined since 1932.
 Some 2 years and 9 months have elapsed since the Special Survey became due and it is submitted for consideration whether the Owners should be asked to arrange for the yacht to be generally examined.

Neither of the Orders should be used for any purpose until it has been furnished. *28.4.39*



© 2020

Lloyd's Register
Foundation

W316-0009