

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

2nd August, 1934.

Dear Sir,

I am favoured with your letter of the 31st ultimo respecting your Screw Schooner Yacht "MARION", from which it is noted that the vessel is still out of commission and is lying at her moorings.

In the circumstances, I have the pleasure to state that so long as the vessel is laid up the Committee will not require the screwshaft to be drawn for examination nor the Boiler Survey carried out, provided steam is not raised therein for any purpose.

Should, however, the vessel be placed in commission these surveys will require to be held, and the class of the yacht has been allowed to remain in the Society's Register of Yachts on this understanding.


I am, Dear Sir,

Yours faithfully,

Coryson

Clerk to the
Classification Committee.

Philip E. Shephard, Esq.,
New Ideal Homesteads, Ltd.,
Ideal House,
Carlton Road,
ERITH, Kent.



Lloyd's Register
Foundation