

POSTPONED SURVEYS.

Case of the Steel Screw Schooner Yacht "MARION"
 3626 in ^{Yacht} Reg. Bk. 715 tons, Built 1896-1 mo.
 +100A1 9.23 Owner P. E. Shephard, Esq.
 s.s. Pts. 3rd No. 3 - 7.32
 +LMC 7.32 Port of Registry Portsmouth
 37.32

Due Boiler Survey became due at the end of July, 1933.
Screwshaft Survey became due at the end of July 1934.

In reply to enquiry regarding the above surveys the Owner writes as follows:-

"I wrote you on receipt of your previous communication, stating that the 'MARION' had not been in commission for two years, and up to date has been lying at her moorings. Under these circumstances I presume it is absolutely unnecessary to have any survey made, and seeing that the boat has not been used for some years, I should like to know whether it is necessary to remove the screwshaft for examination."

Submitted the owner be informed that the screwshaft need not be drawn for examination until the vessel goes into commission.

Committee's Minute *LB*

AL
 18-34

ML

2/2/34

© 2020

51 FEB 1935

FRI. 23 AUG 1935

FRI. 23 FEB 1936

ed ML Deferred ML Deferred

Lloyd's Register Foundation

W316-0041