



TELEGRAMS · IDEAL, ERITH.
TELEPHONE · ERITH 543, 544.

NEW IDEAL HOMESTEADS LTD

JOINT MANAGING DIRECTORS: L. H. P. MEYER · P. E. SHEPARD

HEAD OFFICE:
IDEAL HOUSE, CARLTON ROAD, ERITH, KENT.

LOYD'S REGISTER
RECEIVED
30 MAY 1934

OUR REF. PES/JB.

Tuesday:
29th May
1934

The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
LONDON, E.C.3.

Dear Sir,

I am in receipt of your letter
of the 25th with regard to the 'Marion'.

I understand this boat has not
been used for two years, and I was
unaware that the Boiler Survey was
necessary.

As I am an absolute novice with
regard to this, I shall be glad if you
will kindly give me full particulars
of the time etc. that will be taken
in doing the necessary work.

The boat is on permanent moorings
at Sandbanks, Poole Harbour.

Yours faithfully,

Philip E. Shepard



© 2020

Lloyd's Register
Foundation

W316-0046

Referred to the Chief Engineer Surveyor

30 MAY 1934

Also for Mr. Oliver to note

Submitted the report he
informed that in survey
the boiler is required until it is
intended to raise steam. It is
is done, a survey of the boiler
particulars of the boiler
for a S.S. should be sent to him.

9279 20/5/34



© 2020

Lloyd's Register
Foundation