

So. Sch. "LILY MAID IV"


Messrs. L. Gardner & Son's Engines.

Capt. Rumbeld called at this Office to-day and asked that the Manchester Surveyors might be advised that the arrangements for indicating the direction in which the engines are running, which the Paris Surveyors/^{suggested} should be fitted at the bridge, are in hand.

He further desired that the Surveyors should be asked to take special care to ensure that all valves and fittings of the air reversing control system should be absolutely air tight.

It is submitted the Manchester Surveyors should be advised.

L 6/9/27



6. 9. 27.

© 2020

Lloyd's Register
Foundation

W316-0104