

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

3 FEB 1937

VESSEL'S NAME \_\_\_\_\_ Yacht "LILY MAID LV" \_\_\_\_\_ Rpt. \_\_\_\_\_ Msl. \_\_\_\_\_ No. 9157

**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey \_\_\_\_\_

The Marseilles Surveyors report the wood yacht placed in dry dock,<sup>7</sup> the Annual Survey held ~~and minor repairs carried out.~~

On account of damage through grounding a new rudder head of bronze fitted etc. and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 1,37 and notation of A.S.1,37.

16 A1 )  
1,37 Msl. } In the Y.R.  
A.S.Msl.1,37 )



2020  
2.2.37

Lloyd's Register  
Foundation

W316-0210