

1,9,20.

BOARD REPORT on the

*Steel Twin Screw motor yacht "Princess"*

*As requested by the Builders freeboards were assigned to this yacht, but were eventually not cut in on her sides. It is submitted the full fee be charged for the assignment. viz £4.*

*B.W.B. / in Watt.*  
*13/5/24.*



© 2020

Lloyd's Register  
Foundation

WB17-0112