

F.E.

Received by Chief Ship Surveyor 25.6.02

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. yacht "Surf"* Report *Lth.* No. *10126*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>1/20" less but next strake below increased 1/20" to make the side plating flush.</i>	
Spar Sheerstrake . .		
Description of Framing:— <i>Ordinary.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ∇ 100 A 1 ("Steel") in the yacht Register as recommended.

∇ 100 A 1 ("Steel")
in the yacht Register.
1 DR.

BK 7 1/2" 5BH Cem. Plogh' AYCP



© 2019

Lloyd's Register Foundation
C. N. J.
25/6/02

W319-0091