

COPY.

# Lloyd's Register of Shipping.



Port of LIVERPOOL.

12th. December, 1941.

This is to Certify that

P. N. BOYLAN.

the undersigned Surveyor to this Society did at the request of

the Owners' Representative survey the M.V. "EMPIRE SPRING", 6946 tons gross register of Greenock whilst in Herculanum Dry Dock, Liverpool, on December 7th. & 8th, 1941 on account of damage to shell plating (S.S.). The cause of same not being known.

## FOUND.

Bilge strake in way screen bulkhead in Engine Room, starboard side, indented.

Plate in way in 1st. strake above heavily set in.

Plate in way in 2nd. strake above indented.

Plate in way in 3rd. strake above indented.

Screen bulkhead wing plate heavily buckled. Shell bar and 1st. stiffener to same buckled.

Bilge suction strum box lug broken. Boiler blow-down shell connection disturbed.

The above recommendations have been made to place the vessel in as good a condition as ascertained before damage occurred. Temporary repairs have been effected at this time to render the vessel seaworthy.

## RECOMMENDED.

To be released and faired in place.

To be renewed.

To be released and faired in place

To be released and faired in place.

Wing plate to be cropped and part renewed. Shell bar renewed and 1st. stiffener removed, faired and refitted.

Broken casting to be replaced. Boiler blow-down shell connection removed and resecured. Air pipes etc removed for access and refitted. All new and disturbed work to be re-coated.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that: "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."