

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Sc. M.S. "AQUEITY" Rpt. Lon. No. 100687

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

This ship has left Ipswich for Greenhithe to have the machinery installed.

It is submitted the London Surveyors be advised of what remains to complete the survey, and requested to forward a report on Form Rpt.8 when the survey has been completed.

Mr 26/10/34

Reck-

[Signature]

25.10.34

The Certificate of Classification to be endorsed "*Cargo battens not fitted*" and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

W331-0059