

Tube Shaft, diameter *as per Rule* ✓ Screw Shaft, diameter *as per Rule* ✓ Is the { tube } shaft fitted with a

70.

D. Manufacturer.

(Received at London Office 29 JUL 1936 19...)

No. \_\_\_\_\_ Place Sheaf Ironworks, Lincoln. Date Oct. 7th / 19 35.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to furnish their services in connection with the manufacture of three of our Mark '3 VCRZ' 3-Cylinder Vertical Compression Ignition Marine Auxiliary Oil Engines, which we are building against our stock order No. P/IV.5649/51.

9920

40  
ey

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

To the Secretary,

Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.



Ruston & Hornsby Limited,

A. Hall  
Head Buyer.

Lloyd's Register  
Foundation

W335-0074

What pipes pass through the bunkers ✓

How are they protected ✓