

5c, 114.

Alphasia

F.E.

Received by Chief Ship Surveyor 25.9.14

Received from Chief Ship Surveyor _____

VESSEL'S NAME Sheers Pacific Rpt. SL No. 26235

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 80.25 Depth "d" 21.62

Framing: Table No. 3 page 16. Description Bulk Angle as approved

Longitudinal No. 29692

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.8}{}$

Bridge Deck Sheerstrake as per Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A-1. (Steel), as recommended

100A-1. (Steel)
15K (pl steel + pl iron)
WB = em 5B a 11' u 226' f 164' 9875. FPT 825 aPT 1315
FK. 6BK. Cam. Lign at ep. P 33, B 234 F 33'



© 2020 25.9.14
Lloyd's Register
Foundation

W335-024