

Lloyd's Register of Shipping,

342, Argyle Street, Glasgow.

11th January, 1921.

Dear Sir,

In reply to London letter "S" of 10th instant, regarding the boilers of the S.S. "ROWANPARK" and copy of letter from Messrs. Cooper & Greig therewith enclosed I have to state as follows.

As mentioned in 1st Entry report leakage was found at front end bottom seams of both main boilers and was of such a nature as to indicate it would probably increase and not diminish in use; this leakage extended over about a dozen rivets in each boiler.

It was therefore arranged with Mr. Cooper of Messrs. Cooper & Greig and Mr. Morrison, Owner's Superintendent, that as the ship was urgently wanted she should proceed on her voyage and Mr. Cooper agreed to overhaul and make good the defective rivets on the vessel's return in about one month.

The Secretary,
GLASGOW.



© 2020

I am, Dear Sir,

Yours faithfully,

RW Coomber

W338-0061

W338-0063