

Now Done

1m,7.41.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

72 DEC 1941

VESSEL'S NAME EUGENE V. R. THAYER REPORT N.Os No. 5446

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey COMPLETION OF 2ND S.S. No. 2 When due 2.41
Noted

wab.

.....
5.12.41

S.G.N.Yk. 23-12-41.

The Surveyors should be informed it is concluded that the bunkers have been tested, deep tank examined and tested, the machinery spaces, cofferdams, pump room and hand pumps examined.

X



© 2020

Lloyd's Register
Foundation

W35-0004

This vessel is eligible, in my opinion to remain as classes with fresh record of survey and 2nd ss No.2-41.