

4m.11.38.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

*Billader*

Rpt.

*Ldu.*

No. *109513*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey

~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. *3*

This Survey, due *12.39* now ~~partly~~ held

now

~~completed~~, and the following repairs carried out (due to enemy action):—

*Screw shaft & all parts of machinery opened up & examined. Steam pipes tested. Steering engine removed & refitted. Various electric fittings renewed & other minor repairs carried out.*

It is submitted the vessel is eligible to remain as classed, with notation of *+LMC 3.41* as recommended.

*S. 3.41.*

W350-0129

© 2020

Lloyd's Register  
Foundation