

Lloyd's Register of British and Foreign Shipping

HEAD OFFICE: 71, FENCHURCH STREET, LONDON. E.-C.

PORT OF BARCELONA 4 Feb. 1909

1095

TO
ALBERT MUSTON

Surveyor

CALLE DE MALLORCA, 259

LLOYDS REGISTER,
LONDON.

REC'D 3 FEB 1909

ANS'D

Re. Steamer "Delfin" I saw the owners respecting the alteration of the anchors and cables of this vessel in consequence of the increased tonnage due to the permanent closing in of spaces which before were only closed by doors or hatches —

They say that they would be willing to replace these by heavier ones as soon as they were worn or even if those of some of their other steamers required renewal. But that as at present this is not the case they would prefer losing the equipment number 1 —

The owners could not understand why extra sized cables and anchors were required when the vessel remained exactly the same but I pointed out to them that her tonnage had been increased by the alterations.

Yours Sir

Your obedient servant
Albert MustonLloyd's Register
Foundation

Referred to the Chief Ship Surveyor.

al
FEB -8-1909

Also for Mr. S. A. Hill to note.

CM



© 2021

Lloyd's Register
Foundation