

Copy

Port of Bombay.
7th January 1892.

This is to certify that James Moir and A. C. Clark the undersigned Surveyors to this Society did at the request of Captain Calvert and with the Consent of the owners Messrs Williamson Milligan & Co. of Liverpool of the S.S. *Naverly*. 2022 Tons Survey that vessel on completion of the temporary repairs recommended in our Report of the 26th December 1891


We examined the vessel from time to time as the repairs were being proceeded with and find that they have been carried out to our entire satisfaction and we are of opinion that the vessel is now fit to proceed to Calcutta in ballast to complete the repairs to the Hull

Signed J. A. C. Clark

Signed Jas Moir

The following is a List of Ropes, Wires Blocks &c. alleged to have been carried away lost or injured during the stranding of the S.S. *Naverly*.

- 1 Coil 9" Manilla Hawser Carried away as check when ship floated.
- 2 coils 6" Manilla hauling line. Carried away as bow ropes.



© 2021

Lloyd's Register
Foundation

W35785-0018 1/3

- 1 Coil 4" Manilla tackle, falls used up
 1 " 5" " Hauling line used up
 1 " 2 1/2 " Used for stoppers & lashings
 1 " 2" " Used for heaving lines & lashings.
 2 " 3 1/2 " for Slings used in discharging and reshipping cargo.
 2 " 4 1/4 " for falls used in discharging & reshipping cargo.
 1 " 4 1/2 wire tow ropes Carried away
 1 " 2 1/2 Flexible wire used for tackle falls
 2 Thru folds 5 Tons iron blocks broken
 2 Double 16" wooden blocks broken
 Ring bolt on fore Castle deck started bent and broken.
 Belts on Starboard side aft started want rebolting
 Coat on Main Mast cut to pieces.
 Lips broken off the scuppers through the boots bumping against the shipside.
 Staud spikes broken.
 7 Fathoms of Cable, twisted and strained useless 2 1/16
 90 Fathoms 9" Manilla hawsers chafed & worn
 1 Watch tackle 12" blocks with 30 fms 3" Manilla fall or Chain Hooks lost
 35 Fathoms of Cable 2 1/16 lost.

- 4 Large Hooks - lost.
- 2 Cargo lamps lost on raft.
- 1 Coil 6" Hauling line lost with anchor
as guess warp.
- 1 - 5 1/2 Shackle belonging to the wire tow rope
lost.
- 6 Lamps broken while in use in Taupo.



© 2021

Lloyd's Register
Foundation

W35785-001871