

No 140

Port of Bombay
7th January 1892.

James Moir and A.C. Clark —

Captain Calvert and with the consent of the owners Messrs Williamson Milligan and Company of Liverpool of the S.S. "Waverley" 2022 tons burthen that vessel on completion of the temporary repairs recommended in our Report of the 26th December 1891.

We examined the vessel from time to time as the repairs were being proceeded with, and find that they have been carried out to our entire satisfaction and we are of opinion that the vessel is now fit to proceed to Calcutta in ballast to complete the repairs to the hull.

James Moir

A.C. Clark

Leaving port 8/15 a.m.

W35785-002513



© 2021

Lloyd's Register
Foundation

The following is a List of Ropes, Wires, Blocks &c
alleged to have been carried away, lost or injured
during the stranding of the S.S. "Waverley"

- 1 Coil 9' Manila Haws - carried away as soon as ship floated
- 2 Coils 5' Manila Hauling line, carried away as two ropes
- 1 Coil 4" - as tackle falls used up
- 1 " 5" - Hauling line used up
- 1 " 2½" - used for stoppers, and lashings
- 1 " 2" - used for bearing lines and lashings
- 2 " 3½" - fore stays used in discharging & unshipping ^{calm}
- 2 " 4¾" - for falls
- 1 " 4½" wire two ropes carried away
- 1 " 2½ Flexible wire used for tackle falls
- 2 Three folds 5 tons iron blocks broken
- 2 Double 16" wooden blocks broken
- Ring bolt on fore castle deck started bent & broken
- Bitts on starboard side aft started want re bolting
- Boat on main mast cut to pieces
- Lips broken, off the scuppers through the boat bumping against the ship side.
- Handspikes broken
- 7 Cathpons of cable, twisted retained unless 2½"
- 9" Manila haws chafed worn

W35785-00252/3



© 2021

Lloyd's Register
Foundation

2

1 Hatch tackle 2" blocks with 30 fms 3" Manila fall
4 Chain hooks lost
33 Fathoms of cables 2 $\frac{1}{2}$ " lost
4 Large hooks lost
2 Cargo lamps lost in safe
1 coil 5" hauling line lost with anchor & queen wire
1 5 $\frac{1}{2}$ " shackle belonging to the wire known to be lost
6 Lamps broken while in use in tanks

G. G. W. M.
James Morris

W35785-00253



© 2021
Lloyd's Register
Foundation