

COPY. *clerk M. Elfleda*

## Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.

14th April, 1915.

Dear Sirs,

E. I am in receipt of Mr. Lystad's letter of the 7th instant in further reference to the shaft brackets for the Bk. "FINGAL", and with regard to his remarks on this case and that of the Bk. "ELFLEDA" I have to confirm the following telegram which has been sent to you today on the subject, viz:-

"FINGAL originally submitted length propeller brackets  
"cannot be approved Rules require aftermost bearing 25  
"inches ELFLEDA brackets not submitted drawing sent  
"approved only for diameter shafts aftermost bearing  
"should be  $22\frac{1}{2}$  inches".

I have at the same time to point out that plans which require approval should be submitted before the work is so far advanced that modifications cannot be made.

The plans forwarded are being returned to you by Commercial Papers Post.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,  
CHRISTIANIA.



© 2021

Lloyd's Register  
Foundation