

COPY.

Lloyd's Register of British & Foreign Shipping,

29th ~~London~~ ^{London} Street, E.C.

H. Sir,

Reverting to your letter of the 11th and my reply of the 18th August, 1908, relative to the Special Survey No.2 of the Bk."EAST CROFT", I shall be glad if you will ascertain from the Owners and let me know what further arrangements have been made for this inspection to be carried out.

For your information I may add that the Society's Surveyors at Copenhagen reported that the vessel had been examined in a floating dock after grounding. Some temporary repairs were effected but the Surveyors recommended that permanent repairs should be carried out on the vessel's arrival in Europe.

I am, Sir,

Your obedient Servant,

O.C.Sanne Esq.,

CHRISTIANIA.

© 2021
Secretary.Lloyd's Register
Foundation