

POST OFFICE TELEGRAPHS.

CM or BM F


FOR INWARD FOREIGN AND COLONIAL TELEGRAMS.

No. of Telegram. }

Office of Origin

DE CATANIA CUTELLI 208 33 2 5/50- SR

Office Stamp.



from

Service Instructions.

Sent or Sent out at

To

By

TO


= RP = COMMITTEE LONDON = STEAMER ETNA LIBAU HAS PROPELLER SHOVELS
DAMAGED IMPOSSIBLE CHANGE THERE AS NO DANYER CROSSING ONLY SHORTER SPEED
PLEASE WIRE SURVEYOR LIBAU ALLOW DEPARTURE WILL REPAIR ARRIVAL ROUEN OR
ENGLAND = ETNEA

If the accuracy of this Telegram be doubted, a part, or the whole, can be repeated under special conditions, particulars of which can be obtained on application at the office from which it was delivered.

Charges to pay.

N.B.—This form must accompany any inquiry made respecting this Telegram.

Referred to the Chief Engineer Surveyor.



as.
MAR. 1900
Requesting wire

Also for Mr. Hill to note.

no notes
W.S.

95 £

It is submitted that as the Society has no Surveyor
at Liban, the Surveyor should be requested to ask
Lloyd's Agent ~~to appoint~~ to
appoint a competent Engineer to survey damage
& determine whether propeller efficient for voyage.

Td & Lr to Owners
3/3/00

as.
3.3.00



© 2021

Lloyd's Register
Foundation