

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

4th February, 1932.

Dear Sir,

M.

With reference to previous correspondence regarding the examination of the defective links of chain cable originally supplied to the T.S.M.V. "CONCH", I shall be glad if Mr. Dobson will state the length of the link which broke and caused the loss of the anchor and cable, and the internal diameter of the chain pipe.

With regard to the statement contained in Mr. Dobson's letter of the 26th ultimo regarding the link fouling in the chain pipe, and to the fact that the link sheared at the ends, I shall be glad if he can explain in what manner the link could have fouled to cause it to shear in the way it did.

I am, Dear Sir,

Yours faithfully,

Secretary.

The Secretary,

GLASGOW.



© 2019

Lloyd's Register
Foundation

W372-0161