

F.E.

25. 4. 16

*Received from Chief Ship Surveyor*

Stevens "Broekelo"

Rpt.

Robt-

No. 10028

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*

not summary of any reports that have been required and to show the  
 equal features in connection with the case, so that the Classing Comm  
 Extract from Sub-Committee's Report, 24/5/92.)

**RETAIN**

Depth "d

Transverse No.

44

Depth "d"

11. 42

Framing: Table No.

3 page 9

### Description

Single Angle as approved

Longitudinal No.

4920

## Proportions

Length

13.85

Depth

~~Deck~~ Sheerstrake as per Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \* 100A - (Steel) as recommended.

\* 100 A - (Steel)

1 on (Steel). Wall on

Cell DB + 112, 146E. FRT. 59E. APT 41E

FK. 3 BH. Cen. Q 108. B 13. F 20.

W/373 - 0104

26.4.16



The appraised plan of masts should  
be returned & the Surveyors requested to  
amend same to agree with the report  
and the masts on bill.

*M*

RETAIN



© 2020

Lloyd's Register  
Foundation

W373-0104 2/2

W373-0105