

date latest date of internal examination of each boiler?.....  
did the Surveyor examine the Safety Valves of the Main Boiler?

To what pressure were they afterwards adjusted

"JUTA"

Dieppe 22.  
Hul. 53076

BS due 3.45 partly held at Antwerp 6.45.

A number of leaky tubes expanded and stoppers fitted in main boiler at Dieppe and pressure reduced on that account to 160 lbs.

MBS reheld at Hull where all plain and stay tubes were renewed and repairs effected to safety valves and condenser. Pressure restored to 180 lbs.

Screw shaft examined and machined, propeller renewed and bush rewooded after contact damage.

It is submitted that the vessel is eligible for the Record MBS 8.45, DBS 6.45 and S.8.45.



2020  
11.10.45.

Lloyd's Register  
Foundation

W375-0063

to remain as closed with fresh records of T.S-CL 8.45  
at 180 lbs