

COPY.

Steamer "CLAN MACFAR"

In connection with endorsement dated 3th instant,
the following cabled reply has now come to hand from the Batavia
Surveyor, viz:-

CLAN MACFAR's owners proposal probably completed Tuesday
recommend reducing 75 revolutions to 70 in fair and
half speed in bad weather.

It is suggested that a further cablegram should
be sent to the Batavia Surveyor as follows, viz:-

"If repairs carried out according to instructions and
your entire satisfaction, suggest speed be left to
discretion of master".

DLT BUISKOOL

BATAVIA

10. 6. 33

IF REPAIRS CARRIED OUT ACCORDING TO INSTRUCTIONS AND YOUR ENTIRE
SATISFACTION SUGGEST SPEED BE LEFT TO DISCRETION OF MASTER

COMMITTEE



© 2019

Lloyd's Register
Foundation

W377-0201