

# COPY.

Copy of Telegram received from Captain G.A.Neill, Batavia.

Received 8. 6. 1933

Received 8. 6. 33

Sent off at 4.06 p.m.

Captain  
"CLAN MACNAB"

Care Piteasiru, Batavia.

Surveyor not agreeable your suggestion costing £700 sterling  
time 8 days (stop) Recommend crack in shaft cut out and  
new piece oxygen or electric welded in (stop) No metal  
obtainable here to make new length of shaft - estimated time  
of repairs 6 days costing £500 sterling - no contract obtainable)-  
telegraph instructions



© 2019

Lloyd's Register  
Foundation

W377