

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

13th September, 1933.

Dear Sir,

S.

With reference to your letter of the 6th instant respecting the completion of the Special Survey No.3 of the steamer "CLAN MACNAB", I have to inform you that I have been in communication with the Society's Surveyor at Newport regarding the examination of the vessel in dry dock in February last, and in view of his reply I have to say that the dry docking in question will be accepted by the Committee as part of the Special Survey.

I have to add that the Newport Surveyor also states that he does not consider it necessary that the shell plating should be drilled at this time.

To complete the survey on the hull, therefore, the following remains to be done, viz:-

Anchors and cables, chain locker and windlass to be examined and the oil fuel bunker tested.

I am, Dear Sirs,

Yours faithfully,

The Secretary,

GLASGOW.



© 2019
Clerk to the
Classification Committee.

Lloyd's Register
Foundation

W377-0239